

# VCC Error Troubleshooting


01/10/2024 5:03 pm EST

## Description of Issue:

The following error will occur when opening up a camera device in the VCC - the devices will still load in the background, but as soon as the error is acknowledged, the VCC will shut down.

Details: The component 'VideoControlCenter.InheritedContract.RelayControlToggleSidebarView' does not have a resource identified by the URI

'/VideoControlCenter.InheritedContract;component/view/releaycontroltogglesidebarview.xaml'.



## Fixes:

Uninstall all VCC and all VCC drivers. Delete the VCC folder that is in the Manitou directory. Reinstall the VCC base and all drivers required.